



Locations of the Public Calls in 2014

Address	1830 BUENA VISTA SE				
Event ID	388	REPORTING SOURCE	WEB	Complaint Date	1/15/2014
CUSTOMER	ERIC BEACH	311CASE ID	WEB	e-mail	beacheric@comcast.net
CUSTOMER Ph#	270-9165	SharePointLink: http://sharepoint.cabq.gov/dmd/storm/STORMWATER%20POLLUTION			
Description:	RAW SEWAGE OVERFLOWING FROM 4 PLEX INTO PARKING LOT AND STREET				
Suspected Facility	APARTMENTS	Type of Complaint	SEWAGE		
Inspection Date	1/30/2014	Number of Field Visits	1	Inspector	SK
Facility Contact	NA	Facility Ph. #	na		
FIELD OBSERVATION	THERE WAS DRY RESIDUE NEAR THE SANITARY LINE CLEAN UP VALVE INDICATING SEWAGE OVERFLOW.				
INITIAL ACTION	IT HAS BEEN FIXED, NO ACTION REQUIRED				



Address	3838 BOGAN NE				
Event ID	386	REPORTING SOURCE	WEB	Complaint Date	1/16/2014
CUSTOMER	ANONYMOUS	311CASE ID	WEB	e-mail	
CUSTOMER Ph#		SharePointLink: http://sharepoint.cabq.gov/dmd/storm/STORMWATER%20POLLUTION			
Description:	CHEMICAL WASTE SOLVENT COATING				
Suspected Facility	CAPTIVA GROUP	Type of Complaint	HAZARDOUS MATERIAL		
Inspection Date	1/21/2014	Number of Field Visits	1	Inspector	SK
Facility Contact	NA	Facility Ph. #			
FIELD OBSERVATION	I DID NOT SEE ANY EVIDENC OF DUMPING				
INITIAL ACTION	NO ACTION TAKEN				



Address

5308 CENTRAL AVE SE

Event ID

385

REPORTING SOURCE

311

Complaint Date

1/22/2014

CUSTOMER

STECEY GEORGE

311CASE ID

12065395

e-mail

CUSTOMER Ph#

363-2035

SharePointLink:

Description:

CITIZEN REPORTS AT OCTUPUS CAR WASH SHOWS DRAINAGE FROM THE CAR WASH INTO THE STORM DRAINS ON CENTRAL E NORTH OF THE PROPERTY. CITIZEN SHOW SOME GREENISH COLORED WATER GOING INTO THE DRAIN EVERDAY M-F FOR LAST TWO WEEKS.

Suspected Facility

OCTUPUS CAR WASH

Type of Complaint

COLORD LIQUID

Inspection Date

1/27/2014

Number of Field Visits

1

Inspector

SK

Facility Contact

MANAGER

Facility Ph. #

298-8833

FIELD
OBSERVATION

NO VISIT

INITIAL
ACTION

THE OBSERVED GREEN COLORED WATER ENTERING THE STORM DRAIN INLET AT THIS LOCATION IS CLEAN WATER DRAINING FROM WASHED CARS AFTER LEAVING THE TUNNEL. THE GREEN COLOR IS A HARMLESS, ENVIRONMENT FRIENDLY PRODUCT.

Address	<div>1700 SAUZA DR SW</div>				
Event ID	<div>381</div>	REPORTING SOURCE	<div>311</div>	Complaint Date	<div>1/28/2014</div>
CUSTOMER	<div>ANONYMOUS</div>	311CASE ID	<div>12096890</div>	e-mail	<div>na</div>
CUSTOMER Ph#	<div>na</div>	SharePointLink: http://sharepoint.cabq.gov/dmd/storm/STORMWATER%20POLLUTION			
Description:	<div>CAR HAS BEEN LEAKING OIL IN STREET FOR LAST 4 MONTHS.</div>				
Suspected Facility	<div>HOME</div>	Type of Complaint	<div>OIL</div>		
Inspection Date	<div>1/30/2014</div>	Number of Field Visits	<div>1</div>	Inspector	<div>SK</div>
Facility Contact	<div>RESIDENT</div>	Facility Ph. #	<div>na</div>		
FIELD OBSERVATION	<div>THE OIL SPOT HAS BEEN COVERED WITH OIL ABSORBENT AND IT WILL BE SWEEPED DURING REGULAR STREET SWEEPING DAY. I WENT TO THIS ADDRESS TODAY 1/30/2014 BUT NOBODY WAS HOME.</div>				
INITIAL ACTION	<div>I DISTRIBUTED POLLUTION PREVENTION BROCHURES.</div>				



Address	2509 MESA ST SE				
Event ID	384	REPORTING SOURCE	311	Complaint Date	1/28/2014
CUSTOMER	STREET MAINTENANCE-G		311CASE ID	12080688	e-mail
CUSTOMER Ph#	857-8052	SharePointLink: http://sharepoint.cabq.gov/dmd/storm/STORMWATER%20POLLUTION			
Description:	STREET URGENT PARKED CAR IS LEAKING OIL ONTO THE STREET.				
Suspected Facility	HOME		Type of Complaint	OIL	
Inspection Date	1/30/2014	Number of Field Visits	1	Inspector	SK
Facility Contact	NA	Facility Ph. #			
FIELD OBSERVATION	I DID NOT SEE ANY OIL SPOTS OR LEAKING CAR AT THIS ADDRESS.				
INITIAL ACTION	I DISTRIBUTED POLLUTION PREVENTION BROCHURES AT THIS NEIGHBORHOOD.				



Address	MCDONALDS AT 5324 4TH ST NW				
Event ID	382	REPORTING SOURCE	311	Complaint Date	1/29/2014
CUSTOMER	STEVEN SANCHEZ		311CASE ID	12091326	e-mail na
CUSTOMER Ph#	261-4325		SharePointLink: http://sharepoint.cabq.gov/dmd/storm/STORMWATER%20POLLUTION		
Description:	CITIZEN REPORTING MCDONALDS ON 4TH AND HENDRIX HAS BEEN CLEANING OUT THEIR DUMPSTER AND THE GREASE FROM IT HAS BEEN DRAINING INTO AND INLET INFRONT OF 232 HENDRIX ON THE SOUTHSIDE OF HENDRIX. NO DROP DOWN APPROPRIATE				
Suspected Facility	MCDONALDS		Type of Complaint	COOKING GREASE	
Inspection Date	1/30/2014		Number of Field Visits	1	Inspector SK
Facility Contact	MANAGER		Facility Ph. #	344-6314	
FIELD OBSERVATION	I SAW GREASE COMING OUT FROM THE DUMPESTER AREA. I SPOKE TO THE MANAGER ON THIS ISSUE BUT HE DID NOT KNEW HOW IT HAPPENED.				
INITIAL ACTION	I ASKED HIM TO CLEAN UP THE AREA AND TO MAKE SURE THAT HIS GREASE TANK DO NOT OVERFLOW, ALSO I GAVE HIM SOME POLLUTION PREVENTION BROCHURES.				



Address

6723 FORREST HILLS NE

Event ID

383

REPORTING SOURCE

311

Complaint Date

1/29/2014

CUSTOMER

ANONYMOUS

311CASE ID

12087521

e-mail

na

CUSTOMER Ph#

na

SharePointLink:

<http://sharepoint.cabq.gov/dmd/storm/STORMWATER%20POLLUTION>

Description:

PER CITIZEN HE SAID THAT PERSON LIVING AT THIS ADDRESS IS THROWING DROG DROPPINGS OVER WALL INTO ARROYO

Suspected Facility

ARROYO

Type of Complaint

DOG POOPS

Inspection Date

1/30/2014

Number of Field Visits

1

Inspector

SK

Facility Contact

RESIDENT

Facility Ph. #

na

FIELD
OBSERVATION

I WENT TO THIS ADDRESS BUT NOBODY WAS HOME, I LEFT A NOTE FOR THE RESIDENT TO CLEAN UP THE STUFF THAT THEY THROW AND TO STOP THROWING ANY MORE DOG POOPS OVER THE FENCE TO THE ARROYO.I DISTRIBUTED SOME POLLUTION PREVENTION BROCHURES AT THIS NEIGHBORHOOD.

INITIAL
ACTION

I WENT TO THIS ADDRESS BUT NOBODY WAS HOME, I LEFT A NOTE FOR THE RESIDENT TO CLEAN UP THE STUFF THAT THEY THROW AND TO STOP THROWING ANY MORE DOG POOPS OVER THE FENCE TO THE ARROYO.I DISTRIBUTED SOME POLLUTION PREVENTION BROCHURES AT THIS NEIGHBORHOOD.



Address

9798 COORS BLVD NW

Event ID

380

REPORTING SOURCE

311

Complaint Date

1/30/2014

CUSTOMER

LYNE CORDOVA

311CASE ID

12093506

e-mail

na

CUSTOMER Ph#

269-3700

SharePointLink:

<http://sharepoint.cabq.gov/dmd/storm/STORMWATER%20POLLUTION>

Description:

CITIZEN HAS PICTURES OF OIL DUMPING IT IS FROM AN AUTO BODY WORK SHOP LOCATED IN FRONT OF ADDRESS AT BUILDING B. CITIZEN WOULD LIKE A CALL REGARDING THIS REQUEST. CITIZEN WOULD LIKE SOMEONE TO GO OUT ASAP TO LOOK AT ILLEGAL DUMPING.

Suspected Facility

INTEGRITY AUTOMOTIVE - LUXURY 4 LE

Type of Complaint

OIL

Inspection Date

1/31/2014

Number of Field Visits

1

Inspector

SK

Facility Contact

MANAGER

Facility Ph. #

899-1897

FIELD
OBSERVATION

I SAW DRY RESIDUE SPOT ON THE PARKING LOT OF THE NEXT DOOR BUSINESS PROPERTY.

INITIAL
ACTION

I SPOKE TO THE MANAGER TODAY 1/31/2014 REGARDING THIS ISSUE, HE SAID THAT THERE WAS NO OIL IN THE WATER, THEY JUST WASHED A CAR. I TOLD HIM THAT THEY MUST MAKE SURE NO OIL SHOULD BE DUMPED. HE AGREED TO DO SO.



Address

2844 JOHN SE

Event ID

387

REPORTING SOURCE

311

Complaint Date

2/5/2014

CUSTOMER

ANDREW TORRES

311CASE ID

12091432

e-mail

na

CUSTOMER Ph#

226-7823

SharePointLink:

<http://sharepoint.cabq.gov/dmd/storm/STORMWATER%20POLLUTION>

Description:

CHANGING OIL AND LETTING THE WASTE OIL DRAIN INTO THE STORM DRAIN.

Suspected Facility

STREET

Type of Complaint

OIL

Inspection Date

2/7/2014

Number of Field Visits

1

Inspector

SK

Facility Contact

RESIDENT

Facility Ph. #

na

FIELD
OBSERVATION

I SAW AN OIL SPOT COVERED WITH DIRT

INITIAL
ACTION

I SPOKE TO THE RESIDENT TODAY 2/7/2014 REGARDING THIS ISSUE, HE TOLD ME THAT THE OIL SPILL WAS AN ACCIDENT AND HE ALREADY CLEANED THE AREA AND TOOK THE DRAINED OIL TO RECYCLING PLACE. I ALSO DISTRIBUTED POLLUTION PREVENTION BROCHURES AT THIS NEIGHBORHOOD.



Address	TIJERAS ARROYO EAST OF 4 HILLS				
Event ID	389	REPORTING SOURCE	WEB	Complaint Date	2/6/2014
CUSTOMER	TOM ST. AUBIN	311CASE ID	WEB	e-mail	saintaubin@juno.com
CUSTOMER Ph#	717-1373	SharePointLink: http://sharepoint.cabq.gov/dmd/storm/STORMWATER%20POLLUTION			
Description:	CARPET REMNANTS,PLASTIC STORAGE BIN PARTS, WOOD CRATE.OIL CONTAINERS				
Suspected Facility	ARROYO	Type of Complaint	TRASH		
Inspection Date	2/7/2014	Number of Field Visits	1	Inspector	SK
Facility Contact	NA	Facility Ph. #	na		
FIELD OBSERVATION	I DID NOT SEE ANY OF THE LISTED ITEMS.				
INITIAL ACTION	I E-MAILED THE REPORTER ASKING A BETTER DESCRIPTION OF THE LOCATION, BUT I DID NOT RECEIVE ANY RESPONSE FROM HIM.				



Address	PITA TAZA GRILL AT 7441-A PASEO DEL NORTE				
Event ID	390	REPORTING SOURCE	E-MAIL	Complaint Date	2/14/2014
CUSTOMER	NMDOT	311CASE ID	E-MAIL	e-mail	TimothyR.Trujillo@state.nm.us
CUSTOMER Ph#	798-6690	SharePointLink: http://sharepoint.cabq.gov/dmd/storm/STORMWATER%20POLLUTION			
Description:	GREASE ENTERING THE ROW OF NMDOT FROM THIS RESTURANT				
Suspected Facility	PITA TAZA GRILL	Type of Complaint	COOKING GREASE		
Inspection Date	2/19/2014	Number of Field Visits	1	Inspector	SK
Facility Contact	MANAGER	Facility Ph. #			
FIELD OBSERVATION	I SPOKE TO THE MANAGER ON THIS ISSUE, HE TOLD ME THAT IT WAS AN ACCIDENT THAT THE GREASE TANK SPILL. HE SAID THAT HE HIRED ATLAS CLEAN UP SERVICES TO DEGREASE ALL THESE AREAS AND DISPOSE THE WASTE.				
INITIAL ACTION	I GAVE HIM POLLUTION PREVENTION BROCHURES.				



Address	10427 CANTACIELO NW				
Event ID	392	REPORTING SOURCE	311	Complaint Date	2/19/2014
CUSTOMER	JENNIFER PEREZ		311CASE ID	12139891	e-mail
CUSTOMER Ph#	702-5533	SharePointLink: http://sharepoint.cabq.gov/dmd/storm/STORMWATER%20POLLUTION			
Description:	OIL SPILLED IN MIDDLE OF THE STREET				
Suspected Facility	STREET		Type of Complaint	OIL	
Inspection Date	2/19/2014	Number of Field Visits	1	Inspector	SK
Facility Contact	NA		Facility Ph. #	na	
FIELD OBSERVATION	I SAW A BIG DRIED OIL/HYDRAULIC FLUID SPOT AT 10423 AND 10427 CANTACIELO NW, IT WAS COMPLETELY DRIED AND IT DID NOT NEED TO TAKE FURTHER ACTION.				
INITIAL ACTION	NO ACTION NEEDED				



Address	LOS ALTOS PARK AT COPPER AND ERBBE				
Event ID	393	REPORTING SOURCE	PH CALL	Complaint Date	2/20/2014
CUSTOMER	DAVID SALAS	311CASE ID	E-MAL	e-mail	na
CUSTOMER Ph#	768-5347	SharePointLink: http://sharepoint.cabq.gov/dmd/storm/STORMWATER%20POLLUTION			
Description:	THERE WAS A VEHICLE ACCIDENT (CAR RAN OVER THE FENCE INTO CITY PROPERTY) THAT OCCURRED NEAR THE LOS ALTOS GOLF COURSE WHICH CAUSED MOTOR OIL TO BE SPILLED ON CITY PROPERTY.HOW TO HANDLE THE SPILL.				
Suspected Facility	CITY PARK	Type of Complaint	OIL		
Inspection Date	2/20/2014	Number of Field Visits	1	Inspector	SK
Facility Contact	NA	Facility Ph. #	na		
FIELD OBSERVATION	THERE WAS A MINOR OIL SPILL ON THE SAND				
INITIAL ACTION	KATHEY ASKED THE PARK MANAGER TO REMOVE THE OILED SAND				



Address	2620 TENNESSEE NE		
Event ID	391	REPORTING SOURCE	311
		Complaint Date	2/24/2014
CUSTOMER	RON RUSSELL	311CASE ID	12187057
		e-mail	
CUSTOMER Ph#	489-3968	SharePointLink: http://sharepoint.cabq.gov/dmd/storm/STORMWATER%20POLLUTION	
Description:	PAINTERS OF A BUILDING ALLOWED PAINTS TO RUN INTO GUTTER.		
Suspected Facility	RESIDENT	Type of Complaint	PAINT
Inspection Date	2/26/2014	Number of Field Visits	1
		Inspector	
Facility Contact	RESIDENT	Facility Ph. #	na
FIELD OBSERVATION	I SAW A BIG DRY PAINT RESIDUE AT THIS LOCATION		
INITIAL ACTION	NO BODY WAS HOME, I DISTRIBUTED POLLUTION PREVENTION BROCHURES AT THIS NEIGHBORHOOD		



Address	5308 CENTRAL SE-				
Event ID	394	REPORTING SOURCE	Complaint Date		2/24/2014
CUSTOMER	BRANDY CABIC	311CASE ID	12182961	e-mail	
CUSTOMER Ph#	203-3315	SharePointLink: http://sharepoint.cabq.gov/dmd/storm/STORMWATER%20POLLUTION			
Description:	COOLANTS AND ANTIFREEZE IS DRAINING FROM THE BUSINESS OUT INTO THE STREET				
Suspected Facility	OCTOPUS CAR WASH	Type of Complaint		COLORD LIQUID	
Inspection Date	2/26/2014	Number of Field Visits	1	Inspector	SK
Facility Contact	MANAGER LUIS RAMIREZ	Facility Ph. #	265-1507		
FIELD OBSERVATION	THE GREEN LIQUID DRIPPING FROM THE WASHED CARS IS NOT COOLANT, IT IS A DYE ADDED TO THE CARWASH WATER STREAM JETS, IT IS ENVIRONMENTALLY SAFE.				
INITIAL ACTION	I ASKED THE MANAGER TO TRY TO KEEP THE DRAINING WATER TO THE GUTTER IS MINIMUM AS POSSIBLE. I GAVE HIM SOME OF POLLUTION PREVENTION BROCHURES FOR HIS EMPLOYEE.				



Address

8243 REGAL MIST LP SW

Event ID

395

REPORTING SOURCE

Complaint Date

2/27/2014

CUSTOMER

ANONYMOUS

311CASE ID

12194888

e-mail

na

CUSTOMER Ph#

na

SharePointLink:

<http://sharepoint.cabq.gov/dmd/storm/STORMWATER%20POLLUTION>

Description: MOTOR OIL IN DRIVE WAY AND FLOWING DOWN THE STREET.

Suspected Facility

CAR PARKED ON DRIVEWAY

Type of Complaint

OIL

Inspection Date

2/28/2014

Number of Field Visits

1

Inspector

SK

Facility Contact

RESIDENT

Facility Ph. #

na

FIELD
OBSERVATION

I SAW A BIG OIL SPOT UNDER A CAR PARKED ON THE DRIVEWAY, SOME OF THE OIL WAS FLOWING TO THE SIDEWALK. ALSO I SAW A FEW OIL SPOTS ON THE STREET AT THIS LOCATION.

INITIAL
ACTION

I SPOKE TO THE RESIDENT ON 2/28/2014 REGARDING THE OIL SPILL ON THE SIDEWALK, SHE TOLD ME THAT THE OIL SPILL WAS AN ACCIDENT AND THEY ARE GOING TO GET RID OF BROKEN CAR VERY SOON AND THEY WILL CLEAN UP THE AREA. I COVERED THE OIL SPOTS WITH OIL ABSORBENT



Address	<div>10554 VISTA BELLA PL NW</div>				
Event ID	<div>396</div>	REPORTING SOURCE	Complaint Date		<div>2/28/2014</div>
CUSTOMER	<div>DAVID MUELLER</div>	311CASE ID	<div>12182390</div>	e-mail	<div>NA</div>
CUSTOMER Ph#	<div>898-1991</div>	SharePointLink: http://sharepoint.cabq.gov/dmd/storm/STORMWATER%20POLLUTION			
Description:	<div>THERE WAS A VAN THAT DUMPED SOME ITEMS IN THE INLET STORM DRAIN AT THIS LOCATION. A WHITE VAN THAT SAYS UPHOLSTERY AND CARPET CLEANING 417-9530 THAT IS DUMPING LIQUIDS INTO STORM SEWER.THIS VAN DUMPED LAS 2 TIMES.</div>				
Suspected Facility	<div>CARPET CLEANING CO</div>	Type of Complaint		<div>CARPET CLEANING</div>	
Inspection Date	<div>2/28/2014</div>	Number of Field Visits	<div>1</div>	Inspector	<div>SK</div>
Facility Contact	<div>MANAGER</div>	Facility Ph. #	<div>417-9530</div>		
FIELD OBSERVATION	<div>I VISIT THE SITE ON 2-28-2014 AND I DID NOT SEE ANY KIND OF DERBIES ON THE STORM INLET GRATES.I ALSO SPOKE TO THE CALLER.</div>				
INITIAL ACTION	<div>I SPOKE TO THE MANAGER OF THIS CARPET CLEANING CO REGARDING THIS INCIDENT, HE TOLD ME THAT THEY JUST DUMPED CLEAN WATER TO EMPTY THEIR TANK. I ALSO DISTRIBUTED POLLUTION PREVENTION BROCHURES AT THIS NEIGHBORHOOD</div>				



Address	13215 MOUNTAIN NE		
Event ID	397	REPORTING SOURCE	Complaint Date 3/12/2014
CUSTOMER	LARRY HERRERA	311CASE ID 12244731	e-mail
CUSTOMER Ph#	980-2073	SharePointLink: http://sharepoint.cabq.gov/dmd/storm/STORMWATER%20POLLUTION	
Description:	HE WANTS TO KNOW WHO WOULD BE RESPONSIBLE TO CLEAN UP A DRAINAGE AREA BEHIND HIS HOUSE?		
Suspected Facility	DRAINAGE EASEMENT	Type of Complaint	SEDIMENT
Inspection Date	3/14/2014	Number of Field Visits	1
Inspector	SK		
Facility Contact	STREET MAINTENANCE	Facility Ph. #	
FIELD OBSERVATION	THIS IS A CITY DRAINAGE EASEMENT, I SAW A LOT OF SEDIMENTS AND TRASH IN THE EASEMENT		
INITIAL ACTION	ASKED ARROYO CLEANING CREW TO CLEN UP THIS CHANNEL.		



Address

1612 CULLEN LN NE

Event ID

398

REPORTING SOURCE

Complaint Date

3/14/2014

CUSTOMER

MARK ROBERTSON

311CASE ID

12257562

e-mail

CUSTOMER Ph#

514-9274

SharePointLink:

Description:

CAN I DRAIN POOL INTO GUTTER/STORM DRAIN?

Suspected Facility

HOME

Type of Complaint

GREY WATER

Inspection Date

3/14/2014

Number of Field Visits

0

Inspector

SK

Facility Contact

CALLER

Facility Ph. #

514-9274

FIELD

OBSERVATION

NO VISIT

INITIAL
ACTION

IT IS OKAY TO DISCHARGE THE WATER AT SLOW RATE IF THERE IS NO RESIDUAL CHLORINE IN IT, OR IT CAN BE DISCHARGED AFTER IT IS DECHLORINATED BY DECHLORINATED TABLETS. I CALLED THE CALLER AND INFORMED HIM ABOUT THIS.

Address	<div>121 GENERAL STILWELL NE</div>		
Event ID	<div>399</div>	REPORTING SOURCE	Complaint Date <div>3/27/2014</div>
CUSTOMER	<div>ENVI. HEALTH</div>	311CASE ID	<div>E-MAL</div> e-mail <div></div>
CUSTOMER Ph#	<div>768-2658</div>	SharePointLink: http://sharepoint.cabq.gov/dmd/storm/STORMWATER%20POLLUTION	
Description:	<div>OIL AND FLUID SPILL ON THE STREET</div>		
Suspected Facility	<div>AUTO SHOP</div>	Type of Complaint	<div>OIL & ANTIFREEZE</div>
Inspection Date	<div>4/2/2014</div>	Number of Field Visits	<div>1</div> Inspector <div>SK</div>
Facility Contact	<div>MANAGER</div>	Facility Ph. #	<div></div>
FIELD OBSERVATION	<div>I SAW SEVERAL OIL SPOTS AROUND THIS AREA</div>		
INITIAL ACTION	<div>I ASKED THE MANAGER TO CLEAN UP THE OIL SPOTS AND STOP DUMPING OIL TO THE STREET. ALSO, I GIVE HIM SOME BROCHURES</div>		



Address

11136 MALAGUENA NE

Event ID

407

REPORTING SOURCE

Complaint Date

4/1/2014

CUSTOMER

ROBERT STRONG

311CASE ID

E-MAIL

e-mail

rstrong@abcwua.org

CUSTOMER Ph#

SharePointLink:

<http://sharepoint.cabq.gov/dmd/storm/STORMWATER%20POLLUTION>

Description:

I HAVE A CONTRACTOR IN MY NEIGHBORHOOD WHO CLEANS HIS PAINT CANS INTO THE GUTTER. YOU CAN FOLLOW THE STAINS UP TO 11136 MALAGUENA NE. CAN THIS BE REPORTED TO SOMEONE IN YOUR GROUP?

Suspected Facility

HOME

Type of Complaint

PAINT

Inspection Date

4/24/2014

Number of Field Visits

1

Inspector

SK

Facility Contact

RESIDENT

Facility Ph. #

FIELD
OBSERVATION

THE WHIT DRY PAINT RESIDUE WAS VISIBLE COMING FROM THIS ADDRESS.

INITIAL
ACTION

NOBODY WAS HOME AT THE TIME OF MY VISIT. I LEFT POLLUTION PREVENTION BROCHURES AT THIS ADDRESS AND THE REST OF THIS NEIGHBORHOOD.



Address	507 MARTINEZ DR NE		
Event ID	400	REPORTING SOURCE	Complaint Date 4/14/2014
CUSTOMER	JESUS APODACA	311CASE ID 12348825	e-mail na
CUSTOMER Ph#	250-5697	SharePointLink: http://sharepoint.cabq.gov/dmd/storm/STORMWATER%20POLLUTION	
Description:	SEWAGE LEAKING FROM THE FRONT YARD OF THIS PROPERTY AND LEAKING INTO THE STREET		
Suspected Facility	HOME	Type of Complaint	SEWAGE
Inspection Date	4/15/2014	Number of Field Visits	1 Inspector SK
Facility Contact	NA	Facility Ph. #	na
FIELD OBSERVATION	NO SEWER OVERFLOW FOUND, IT HAS BEEN FIXED		
INITIAL ACTION	NO ACTION REQUIRED		



Address	10804 CHOCHITI SE NO.27		
Event ID	401	REPORTING SOURCE	Complaint Date 4/15/2014
CUSTOMER	ANONYMOUS	311CASE ID	12369158 e-mail
CUSTOMER Ph#	na	SharePointLink: http://sharepoint.cabq.gov/dmd/storm/STORMWATER%20POLLUTION	
Description:	SEMI TRAILER LEAKING OIL ON THE STREET		
Suspected Facility	TRAILER	Type of Complaint	OIL
Inspection Date	4/15/2014	Number of Field Visits	1 Inspector SK
Facility Contact	RESIDENT	Facility Ph. #	na
FIELD OBSERVATION	I SAW SOME OIL SPOTS		
INITIAL ACTION	I SPOKE TO THE RESIDENT AND DISTRIBUTED P2 BROCHURES		



Address

8224 LOMA DEL NORTE NE

Event ID

406

REPORTING SOURCE

Complaint Date

4/23/2014

CUSTOMER

PAUL RIVERA

311CASE ID

12401063-12401051

e-mail

topchip@yahoo.com

CUSTOMER Ph#

SharePointLink:

<http://sharepoint.cabq.gov/dmd/storm/STORMWATER%20POLLUTION>

Description:

SUV PARKED IN FRONT OF HOUSE FOR SEVERAL WEEKS NOW WITH MAJOR OIL SPILL UNDERNEATH VEHICLE. SEVERAL GALLONS OF OIL OR TRANSMISSION FLUID WITH STRONG GASOLINE SMELL LAYING ON STREET. CAR IS POSSIBLY DISABLED OR ABANDONED AND NEEDS TO BE MOVED.

Suspected Facility

HOME

Type of Complaint

OIL

Inspection Date

4/24/2014

Number of Field Visits

1

Inspector

Facility Contact

RESIDENT

Facility Ph. #

FIELD
OBSERVATION

THE RESIDENT AT THIS ADDRESS WAS NOT HOME AT THE TIME OF MY VISIT TODAY 4/24/2014. THE PAVEMENT UNDER THE VEHICLE WAS CLEAN AND THERE WAS NO OIL DRIPPING, ALSO THE VEHICLE HAD LEGAL VALID LICENCE PLATE AND IN GOOD SHAPE.

INITIAL
ACTION

NO ACTION IS NECESSARY. I LEFT A POLLUTION PREVENTION BROCHURE ON THE VEHICLE AND ALSO DISTRIBUTED POLLUTION PREVENTION BROCHURES AT THIS NEIGHBORHOOD.



Address	5600 CROWNRIDGE NW				
Event ID	405	REPORTING SOURCE	311	Complaint Date	4/24/2014
CUSTOMER	ANONYMOUS		311CASE ID	12402220	e-mail
CUSTOMER Ph#		SharePointLink: http://sharepoint.cabq.gov/dmd/storm/STORMWATER%20POLLUTION			
Description:	OIL IS RUNNING DOWN THE STREET				
Suspected Facility	HOME		Type of Complaint	OIL	
Inspection Date	4/28/2014	Number of Field Visits	1	Inspector	SK
Facility Contact	RESIDENT		Facility Ph. #		
FIELD OBSERVATION	THE VEHICLE HAS BEEN REMOVED AND THE OIL WAS COVERED WITH ABSORBENT,				
INITIAL ACTION	I ADDED SOME MORE ABSORBENT TO COMPLETE THE REMOVAL OF THE OIL.THE ABSORBENT WILL BE SWEEPED NEXT STREET SWEEPING DAY.I ALSO DISTRIBUTED POLLUTION PREVENTION BROCHURES AT THIS NEIGHBORHOOD				



Address

5300 RAWLINGS NE

Event ID

416

REPORTING SOURCE

Complaint Date

4/24/2014

CUSTOMER

CRAIG EVANS

311CASE ID

WEB

e-mail

crevans17@gmail.com

CUSTOMER Ph#

310-3047

SharePointLink:

Description:

THE SEWAGE SMELL AT MY HOME IS UNBEARABLE. AS SOON AS I WALK OUT FRONT OR BACK OF MY HOME I AM PUNCHED IN THE FACE WITH THE SMELL OF SEWAGE. THE SMELL SEEMS TO BE WORSE IN THE FRONT, AND BASED ON WIND DIRECTION (EAST), IT SEEMS TO BE COMING FROM RAWLINGS

Suspected Facility

SANITARY LINES

Type of Complaint

FOUL ODOR

Inspection Date

4/24/2014

Number of Field Visits

0

Inspector

SK

Facility Contact

ABCWUA

Facility Ph. #

FIELD
OBSERVATION

THIS IS NOT STORM LINE ISSUE-NO SITE VISIT

INITIAL
ACTION

FORWARDED TO ABCWUA

Address	4913 MENAUL NE ZIA AUTO		
Event ID	402	REPORTING SOURCE	Complaint Date 4/25/2014
CUSTOMER	ANONYMOUS	311CASE ID 12360561	e-mail
CUSTOMER Ph#		SharePointLink: http://sharepoint.cabq.gov/dmd/storm/STORMWATER%20POLLUTION	
Description:	THIS BUSINESS IS WASHING CARS AND THEREIS ALWAYS STANDING WATER BEHIND SHOP IN THE ALLEY.CITIZEN SMELL A CHEMICAL SMELL ONCE AND IS WONDER IF CHEMICAL AS PASSING WITH THE WATER OFF THEIR PROPERTY.		
Suspected Facility	ZIA AUTO	Type of Complaint	CAR WASHING
Inspection Date	5/5/2014	Number of Field Visits	1
Facility Contact	MANAGER	Inspector	SK
Facility Ph. #			
FIELD OBSERVATION	THERE WAS OILY DRY RESIDUE IN THE ALLEY COMING FROM BACK OF THE SHOP.		
INITIAL ACTION	I SPOKE TO THE MANAGER OF ZIA AUTO BUSINESS REGARDING THE DIRTY WASH WATER COMING OUT FROM THEIR AREA INTO THE ALLEY. HE TOLD ME THAT HE WILL MAKE SURE THAT THE WASH WATER WILL NOT LEAVE HIS YARD TO THE ALLEY. I GAVE HIM SOME POLLUTION PREVENTION BROCHURE		



Address	MARTIN LUTHER KING AT BROADWAY TO I-25				
Event ID	403	REPORTING SOURCE	Complaint Date		5/8/2014
CUSTOMER	MELISSA LOZOYA	311CASE ID	PH CALL	e-mail	
CUSTOMER Ph#		SharePointLink: http://sharepoint.cabq.gov/dmd/storm/STORMWATER%20POLLUTION			
Description:	WHITE SUBSTANCE FLOWING DOWN THE STREET				
Suspected Facility		Type of Complaint		PAINT	
Inspection Date	5/9/2014	Number of Field Visits	1	Inspector	SK
Facility Contact		Facility Ph. #			
FIELD OBSERVATION	I WALKED ALONG THIS STREET FROM BROADWAY TO I-25 AND I COULD NOT SEE ANY WHITE SUBSTANCE, PROBABLY THE RAIN LAST NIGHT WASHED OFF ALL THE WHITE SUBSTANCE.				
INITIAL ACTION	NO ACTION WAS NECESSARY				



Address

ZUNI & ARIZONA SE, TACO SANCHEZ FOOD TRUCK

Event ID

404

REPORTING SOURCE

Complaint Date

5/13/2014

CUSTOMER

VERONICA DESERNA

311CASE ID

12474076

e-mail

CUSTOMER Ph#

307-8909

SharePointLink:

<http://sharepoint.cabq.gov/dmd/storm/STORMWATER%20POLLUTION>

Description:

CITIZEN REPORTED SEEING TACO SANCHEZ FOOD TRUCK DUMP LIQUID WASTE FROM UNDERNEATH THE TRUCK INTO STORM DRAIN. CITIZEN SAW CREW OPEN UP UNDERCARRIAGE AND DUMP INTO STORM DRAIN.

Suspected Facility

TACO SANCHEZ FOOD TRUCK

Type of Complaint

FOOD

Inspection Date

5/15/2014

Number of Field Visits

1

Inspector

SK

Facility Contact

OWNER

Facility Ph. #

FIELD
OBSERVATION

I DID NOT SEE ANY DIRTY DRY RESIDUE AT THIS LOCATION AND ALSO THERE WAS NO STORM INLET NEAR BY. THE OWNER OF BUSINESS TOLD ME THAT HE JUST WAS DUMPING CLEAN WATER.

INITIAL
ACTION

I TOLD HIM TO MAKE SURE THAT NO DIRTY WATER WATER TO BE DUMPED TO THE CITY STREET IN THE FUTURE.



Address	5150 A-1 EDITH NE		
Event ID	408	REPORTING SOURCE	Complaint Date 5/21/2014
CUSTOMER	ANONYMOUS	311CASE ID 12499582	e-mail
CUSTOMER Ph#		SharePointLink: http://sharepoint.cabq.gov/dmd/storm/STORMWATER%20POLLUTION	
Description:	CITIZEN SAID THE RADIATOR SHOP AT INCIDENT ADDRESS IS THROW ACIDS,GASOLINE, AND OTHER CHEMICALS DOWN THE DRAIN. ALSO, THERE ARE IN AREAS IN SHOP WITH CONTAINERS OF OPEN CHEMICALS. CITIZEN REQUESTED THAT SHOP BE INSPECTED BY CITY.		
Suspected Facility	JB RADIATOR	Type of Complaint	HAZARDOUS MATERIAL
Inspection Date	5/27/2014	Number of Field Visits	1
Inspector	SK		
Facility Contact	MANAGER	Facility Ph. #	344-1458
FIELD OBSERVATION	I INSPECTED THIS SHOP ON 5/27/2014 AND I DID NOT SEE ANY HAZARDOUS WASTE DUMP AROUND THIS AREA. I SPOKE TO THE MANAGER OF THE SHOP AND HE DENIED DUMPING ANY HAZARDOUS WASTE TO THE STREET OR TO THE STORM INLETS, HE SHOWED ME THE WASHING AND STORAGE TANKS		
INITIAL ACTION	I LEFT SOME POLLUTION PREVENTION BROCHURES AT THIS SHOP		



Address

SEAFOOD BROIL AT 6100 4TH ST NW

Event ID

409

REPORTING SOURCE

Complaint Date

5/29/2014

CUSTOMER

ANONYMOUS

311CASE ID

12533003

e-mail

CUSTOMER Ph#

SharePointLink:

<http://sharepoint.cabq.gov/dmd/storm/STORMWATER%20POLLUTION>

Description:

RAW SEWAGE AND GREASE IS FLOWING FROM THIS RESTUARANT INTO THE STORM DRAINS. NAME OF BUSINESS IS SEAFOOD BROIL.

Suspected Facility

SEAFOOD BROIL RESTURANT

Type of Complaint

SEWAGE

Inspection Date

6/2/2014

Number of Field Visits

1

Inspector

SK

Facility Contact

MANAGER

Facility Ph. #

FIELD
OBSERVATION

THERE WAS NO OVERFLOWED SEWAGE IN THE STREET OR THE PROPERTY, THE OVERFLOW WAS FIXED AND THE AREA HAS BEEN CLEANED UP

INITIAL
ACTION

I SPOKE TO THE MANAGER OF THE RESTAURANT ON 6/2/2014 AND HE TOLD ME THAT THEIR SEWER LINE WAS PLUGGED UP CAUSING OVERFLOW THROUGH THE INSPECTION VALVES. THEY FIX THE PROBLEM AND THERE WAS NO OVERFLOW. I GAVE HIM SOME POLLUTION PREVENTION BROCHURES.



Address

828 MANZANO NE

Event ID

410

REPORTING SOURCE

Complaint Date

5/30/2014

CUSTOMER

MARY BROEMEL

311CASE ID

12537970

e-mail

CUSTOMER Ph#

307-0569

SharePointLink:

<http://sharepoint.cabq.gov/dmd/storm/STORMWATER%20POLLUTION>

Description:

"FROM PROPERTY TO STORM DRAIN GOING SOUTH"
SOMEONE HAS POURED SOMETHING DOWN DRAIN FROM ONE HOUSE, STAINED LENGTH OF STREET, SMALL
AMOUNT MAY HAVE MADE IT TO DRAIN.COMING FROM ADDRESS, DRIED, VERY VISIBLE FROM STAIN, BRIGHT
RUST COLOR.

Suspected Facility

HOME

Type of Complaint

PAINT

Inspection Date

6/2/2014

Number of Field Visits

1

Inspector

Facility Contact

Facility Ph. #

FIELD
OBSERVATION

I SPOKE TO THE HOME OWNER ON 6/2/2014 AND HE TOLD ME THAT HE ACID RUSTIC STAINED HIS CONCRETE
DRIVEWAY USING AN ENVIRONMENTALLY SAFE ACID STAIN. THE RUSTIC COLOR ALONG THE GUTTER WAS
THE RESULT OF WASHING ACCESS STAIN ON THE DRIVEWAY.

INITIAL
ACTION

I DISTRIBUTED POLLUTION PREVENTION BROCHURES AT THIS NEIGHBORHOOD.



Address	1909 4TH ST NW		
Event ID	411	REPORTING SOURCE	Complaint Date 6/2/2014
CUSTOMER	CATHERINE MEXAL	311CASE ID	E-MAIL e-mail cmexal@gmail.com
CUSTOMER Ph#		SharePointLink: http://sharepoint.cabq.gov/dmd/storm/STORMWATER%20POLLUTION	
Description:	THIS CAR-DETAILING BUSINESS ROUTES ITS NASTY WASTE WATER INTO THE STREET. IT HAS SO MUCH BLACK ROAD SLUDGE IN IT THAT THEY'VE ACTUALLY HAD TO DIG A CHANNEL THROUGH THE SLUDGE. THE STREET IS NEVER DRY.		
Suspected Facility	SOUTHWEST IMPORT SUPPLY	Type of Complaint	CAR WASHING
Inspection Date	6/6/2014	Number of Field Visits	1 Inspector SK
Facility Contact	MANAGER	Facility Ph. #	
FIELD OBSERVATION	I SAW THE DIRTY WATER IS COMING OUT OF THIS BUSINESS AND PUDDLES IN THE GUTTER ALONG THE 4TH ST		
INITIAL ACTION	I SPOKE TO THE MANAGER AND ASKED HIM TO STOP WASHING CARS IN THE SHOP, HE AGREED TO DO SO. I GAVE HIM AND THE OTHER BUSINESSES AT THIS LOCATION SOME POLLUTION PREVENTION BROCHURES		



Address

1901 INDIAN PLAZA NE

Event ID

412

REPORTING SOURCE

Complaint Date

6/24/2014

CUSTOMER

ANONYMOUS

311CASE ID

12637016

e-mail

CUSTOMER Ph#

SharePointLink:

Description:

WHITE VAN SAID X STREAM CARPET CLEANERS - NO LICENSE PLATE SEEN, THERE WAS A LARGE BLUE HOSE GOING INTO THE STORM DRAIN FROM THE VAN. 6/23/14 ABOUT 5 PM - HAS BEEN DONE BEFORE.BELIEVE THE CARPETS WERE CLEANED AT CEDARS AND THE INDIAN PLAZA APARTMEN

Suspected Facility

XTREME CLEAN

Type of Complaint

CARPET CLEANING

Inspection Date

6/24/2014

Number of Field Visits

1

Inspector

SK

Facility Contact

MANAGER/OWNER

Facility Ph. #

489-0915

FIELD
OBSERVATION

NO VISIT

INITIAL
ACTION

I SPOKE TO THE MANAGER OF XTREME CARPET CLEANING (489-0915), HE TOLD ME THAT HIS EMPLOYEES ARE TOLD NOT TO DUMP ANY CARPET CLEANING WASTEWATER INTO STORM DRAINS AND HE WILL MAKE SURE THAT THIS WILL NOT HAPPEN AGAIN.ALSO, I SPOKE TO THE MANAGER OF THE APAR

Address	6132 FLOR DE MAYO PL NW				
Event ID	413	REPORTING SOURCE	Complaint Date		6/30/2014
CUSTOMER	TIM WAGNER	311CASE ID	E-MAIL AND PH	e-mail	
CUSTOMER Ph#	349-9805	SharePointLink: http://sharepoint.cabq.gov/dmd/storm/STORMWATER%20POLLUTION			
Description:	PAINT AND AUTOMOTIVE FLUIDS FROM THIS ADDRESS				
Suspected Facility	HOME	Type of Complaint		PAINT	
Inspection Date	6/30/2014	Number of Field Visits	1	Inspector	SK
Facility Contact	RESIDENT	Facility Ph. #			
FIELD OBSERVATION	THERE WAS RED PAINT RESIDUE ALONG THE GUTTER COMING FROM THIS ADDRESS				
INITIAL ACTION	I SPOKE TO THE RESIDENT AND HE TOLD ME THAT IT WAS AN ACCIDENT THAT THEY SPILL A BUCKET OF PAINT. I DISTRIBUTED POLLUTION PREVENTION BROCHURES AT THIS NEIGHBORHOOD.				



Address	109 WELLESLEY SE		
Event ID	414	REPORTING SOURCE	Complaint Date 7/1/2014
CUSTOMER	SALLY FULTON	311CASE ID 12538423	e-mail
CUSTOMER Ph#	255-6533	SharePointLink: http://sharepoint.cabq.gov/dmd/storm/STORMWATER%20POLLUTION	
Description:	WASHING WATER FROM BEER RESTURANT SMELLS BAD		
Suspected Facility	RESTURANT	Type of Complaint	GREY WATER
Inspection Date	7/2/2014	Number of Field Visits 1	Inspector SK
Facility Contact	MANAGER	Facility Ph. #	
FIELD OBSERVATION	THE ALLEY IS PAVED AND IT IS IN BAD CONDITION. THE FLOOR WASHING WATER FROM THE RESTURENT SMELLS BAD AND PONDS IN THE ALLEY.		
INITIAL ACTION	I ASKED THE RESTURANT NOT TO DUMP THEIR WASHING WATER IN TO THE ALLEY.		



Address	13608 COVERED WAGON SE		
Event ID	415	REPORTING SOURCE	Complaint Date 7/1/2014
CUSTOMER	MIKE JOLLEY	311CASE ID	12586000 e-mail
CUSTOMER Ph#	991-0784	SharePointLink: http://sharepoint.cabq.gov/dmd/storm/STORMWATER%20POLLUTION	
Description:	OIL SPOTS ON THE STREET		
Suspected Facility	HOME	Type of Complaint	OIL
Inspection Date	7/1/2014	Number of Field Visits	1 Inspector SK
Facility Contact	RESIDENT	Facility Ph. #	
FIELD OBSERVATION	THERE WERE SEVERAL DRIED OIL SPOTS AT THIS LOCATION.RESIDENT WAS NOT HOMEAT THE TIME OF THE VISIT.		
INITIAL ACTION	DISTRIBUTED POLLUTION PREVENTION BROCHURES AT THIS NEIGHBORHOOD		



Address

10559 COYOTE CANYON PL NW

Event ID

418

REPORTING SOURCE

Complaint Date

7/9/2014

CUSTOMER

MARIA TROTTER

311CASE ID

12697897

e-mail

CUSTOMER Ph#

977-7809

SharePointLink:

Description:

CITIZEN WANTS TO KNOW WHY IT'S THAT A CLEANING COMPANY CAN DUMP INTO A STORM DRAIN. SHE SAW A CARPET CLEANING VAN DUMPING WASTEWATER INTO A STORM DRAIN

Suspected Facility

CLEANING COMPANY BUSINESS

Type of Complaint

CARPET CLEANING

Inspection Date

7/8/2014

Number of Field Visits

1

Inspector

SK

Facility Contact

CALLER

Facility Ph. #

977-7809

FIELD
OBSERVATION

NO VISIT.SHE SAW A CARPET CLEANING VAN DUMPING WASTEWATER INTO A STORM DRAIN

INITIAL
ACTION

I TOLD THE CALLER THAT DUMPING IS NOT LEGAL AND IF SHE SEE ANOTHER SIMILAR INCIDENT, SHE MAY RECORD THE COMPANY NAME AND CALL US.

Address

4605 BERMUDA NE

Event ID

423

REPORTING SOURCE

Complaint Date

7/10/2014

CUSTOMER

JOYCE SANCHEZ

311CASE ID

12700834

e-mail

CUSTOMER Ph#

301-7028

SharePointLink:

Description:

CITIZEN'S NEIGHBOR IS ATTEMPTING TO CLEAN UP POOL WATER USING CHEMICALS, MAY BE EMPTYING--IS UNSURE OF SAFETY ISSUES, WOULD LIKE CONTACT, THANKS

Suspected Facility

SWIMMING POOL

Type of Complaint

GREY WATER

Inspection Date

7/28/2014

Number of Field Visits

1

Inspector

SK

Facility Contact

CALLER

Facility Ph. #

301-7028

FIELD
OBSERVATION

NO VISIT

INITIAL
ACTION

THE VOICE MAIL BOX OF THIS PERSON IS FULL, TRIED CALLING SEVERAL TIMES ON 7-29-2014 BUT NO ANSWER.

Address	1102 GRETTA NE		
Event ID	422	REPORTING SOURCE	Complaint Date 7/21/2014
CUSTOMER	ANONYMOUS	311CASE ID 12743053	e-mail
CUSTOMER Ph#		SharePointLink: http://sharepoint.cabq.gov/dmd/storm/STORMWATER%20POLLUTION	
Description:	CITIZEN SEES OWNER OF ADDRESS USING A WATER HOSE TO DRAIN POOL WATER INTO STREET AND SMELLS VERY BAD. CITIZEN NEEDS TO BE ADDRESSED ON THE PROPER WAY TO DRAIN POOL WATER AND MAINTAIN POOL WATER.		
Suspected Facility	HOME	Type of Complaint	SWIMMING POOL
Inspection Date	7/25/2014	Number of Field Visits	1
Facility Contact	RESIDENT	Inspector	SK
Facility Ph. #			
FIELD OBSERVATION	I SPOKE TO THE RESIDENT REGARDING THIS INCIDENT, HE TOLD ME THAT HE DRAINED HIS SWIMMING POOL TO THE FRONT AND BACK YARDS AND VERY SMALL PORTION WENT TO THE STREET BY ACCIDENT. I TOLD HIM THAT HE CAN USE THE SANITARY LINE TO EMPTY HIS SWIMMING POOL.		
INITIAL ACTION	I DISTRIBUTED POLLUTION PREVENTION BROCHURES AT THIS NEIGHBORHOOD.		



Address	1229 COLUMBIA NE		
Event ID	420	REPORTING SOURCE	Complaint Date 7/23/2014
CUSTOMER	ILENE MURPHY	311CASE ID 12751967	e-mail
CUSTOMER Ph#	266-2136	SharePointLink: http://sharepoint.cabq.gov/dmd/storm/STORMWATER%20POLLUTION	
Description:	PLASTIC GREY COLOR DUMPED INTO STORM DRAIN AT ADDRESS		
Suspected Facility	HOME	Type of Complaint	HAZARDOUS MATERIAL
Inspection Date	7/25/2014	Number of Field Visits	1 Inspector SK
Facility Contact	RESIDENT	Facility Ph. #	
FIELD OBSERVATION	THE SOURCE OF DISCHARGE WAS DRAINING THE TURBID WATER FROM A SMALL FISH POND AT 1229. THERE IS NO HARM EFFECTS TO THE ENVIRONMENT FROM THIS DISCHARGE AND CLEANING THE DRY RESIDUE WAS NOT NECESSARY.		
INITIAL ACTION	I DISTRIBUTED POLLUTION PREVENTION BROCHURES AT THIS NEIGHBORHOOD.		



Address	SAINT JOSEPH AND UNSER NW		
Event ID	421	REPORTING SOURCE	Complaint Date 7/23/2014
CUSTOMER	LEON LOVATO	311CASE ID 12710357	e-mail
CUSTOMER Ph#	980-9958	SharePointLink: http://sharepoint.cabq.gov/dmd/storm/STORMWATER%20POLLUTION	
Description:	DUMPING LIQUID SOLUTION INTO ARROYO		
Suspected Facility	LIGHT CONNECTION FIBER SOLUTIONS	Type of Complaint	COLORD LIQUID
Inspection Date	7/23/2014	Number of Field Visits	1
Inspector			
Facility Contact	MANAGER	Facility Ph. #	
FIELD OBSERVATION	NO SITE VISIT		
INITIAL ACTION	I SPOKE TO THE MANAGER OF THIS COMPANY REGARDING THE INCIDENT, HE TOLD ME THAT THEY WENT TO THE DUMPING SITE AND CLEANED UP THE DISPOSED MUD AND HE TERMINATED THAT EMPLOYEE WHO DUMPED.		



Address	BOBCAT BETWEEN DEER AND MORNING GLORY NE		
Event ID	419	REPORTING SOURCE	Complaint Date 7/24/2014
CUSTOMER	CHRISTINE MARSHALL	311CASE ID WEB	e-mail
CUSTOMER Ph#	344-1345	SharePointLink: http://sharepoint.cabq.gov/dmd/storm/STORMWATER%20POLLUTION	
Description:	DUMPING CACTUS INTO ARROYO		
Suspected Facility	OPEN SPACE PARK	Type of Complaint	TRASH
Inspection Date	7/24/2014	Number of Field Visits 1	Inspector SK
Facility Contact	NA	Facility Ph. #	
FIELD OBSERVATION	2 TRUCK LOAD OF CACTUS DUMPED INSIDE OPEN SPACE, THIS AREA BELONG TO THE COUNTY		
INITIAL ACTION	I ASKED THE CALLER TO CONTACT THE OPEN SPACE AT THE COUNTY		



Address	MARBLE BETWEEN EDITH AND FRANCISCAN		
Event ID	424	REPORTING SOURCE	Complaint Date 8/11/2014
CUSTOMER	DIANE DOLAN	311CASE ID	E-MAIL ddolan@cabq.gov
CUSTOMER Ph#	768-3186	SharePointLink: http://sharepoint.cabq.gov/dmd/storm/STORMWATER%20POLLUTION	
Description:	STRONG CHEMICAL ODOR		
Suspected Facility	INLET	Type of Complaint	FOUL ODOR
Inspection Date	8/13/2014	Number of Field Visits	1
Facility Contact	NA	Inspector	SK
	Facility Ph. #	na	
FIELD OBSERVATION	THE INLET AT THE CORNER OF MARBLE AND EDITH HAD A BAD ODOR		
INITIAL ACTION	I ASKED THE SORM CLEANING CREW TO CLEAN UP THIS INLET		



Address	6521 PARADISE NW		
Event ID	425	REPORTING SOURCE	Complaint Date 8/13/2014
CUSTOMER	JEFF WILLIS	311CASE ID	E-MAIL e-mail
CUSTOMER Ph#	878-0517	SharePointLink: http://sharepoint.cabq.gov/dmd/storm/STORMWATER%20POLLUTION	
Description:	DUMPING PAINT IN TO THE ARROYO		
Suspected Facility	DESERT RIDGE DENTAL	Type of Complaint	PAINT
Inspection Date	8/14/2014	Number of Field Visits	1 Inspector SK
Facility Contact	CONTRACTOR (TRINTY)	Facility Ph. #	
FIELD OBSERVATION	THERE WAS SOME WHITE PAINT ON THE GRATE AND NEAR THE OUTFALL TO THE ARROYO AT THIS LOCATION.A CONTRACTOR WAS DOING REMODELING WARK AT THIS ADDRESS.		
INITIAL ACTION	I ASKED THE CONTRACTOR TO STOP DUMPING ANY PAINT INTO THE STORM DRAIN AND THE ARROYO AND TO CLEAN UP THE AREA.I ALSO GAVE HIM SOME POLLUTION PREVENTION BROCHURES.		



Address	9200 CARSON MESA NW		
Event ID	426	REPORTING SOURCE	Complaint Date 8/19/2014
CUSTOMER	JOHN MEDINA	311CASE ID 12845461	e-mail
CUSTOMER Ph#	899-4613	SharePointLink: http://sharepoint.cabq.gov/dmd/storm/STORMWATER%20POLLUTION	
Description:	DUMPING ANTIFREEZE INTO STORM DRAIN		
Suspected Facility	HOME	Type of Complaint	OIL & ANTIFREEZE
Inspection Date	8/21/2014	Number of Field Visits 1	Inspector SK
Facility Contact	NA	Facility Ph. #	
FIELD OBSERVATION	THERE WAS NO 9200 HOUSE NUMBER, PROBABLY WAS 9400.I DID NOT SEE ANY LIQUID AROUND THIS INLET.		
INITIAL ACTION	I DISTRIBUTED POLLUTION PREVENTION BROCHURES AT THIS NEIGHBORHOOD.		



Address	530 UTAH SPACE 56		
Event ID	427	REPORTING SOURCE	Complaint Date 8/20/2014
CUSTOMER	ANONYMOUS	311CASE ID	WEB e-mail na
CUSTOMER Ph#	na	SharePointLink: http://sharepoint.cabq.gov/dmd/storm/STORMWATER%20POLLUTION	
Description:	DUMPING LAUNDRY WASHWATER TO THE STREET		
Suspected Facility	MOBILE HOME	Type of Complaint	LAUNDRY CLEANING
Inspection Date	8/25/2014	Number of Field Visits	1 Inspector SK
Facility Contact	RESIDENT	Facility Ph. #	
FIELD OBSERVATION	THE AREA WAS DRY AND THERE WAS NO EVIDENCE OF DUMPING ANY THING TO THE STREET. THE RESIDENT DENIED HAVING LUNDRY MACHINE		
INITIAL ACTION	I DISTRIBUTED POLLUTION PREVENTION BROCHURES AT THIS PARK.		



Address	10300 MENAUL NE SUIT 8-9			
Event ID	428	REPORTING SOURCE	Complaint Date	8/25/2014
CUSTOMER	AARON COFFMAN	311CASE ID	PH CALL TO EHD	e-mail
CUSTOMER Ph#	222-9503	SharePointLink: http://sharepoint.cabq.gov/dmd/storm/STORMWATER%20POLLUTION		
Description:	AUTOMOTIVE FACILITY AT THIS ADDRESS MAY BE DUMPING ANTIFREEZE			
Suspected Facility	AUTO SHOP	Type of Complaint	ANTIFREEZE	
Inspection Date	8/27/2014	Number of Field Visits	1	Inspector SK
Facility Contact	MANAGER	Facility Ph. #		
FIELD OBSERVATION	I SPOKE TO THE MANAGER OF THIS AUTO SHOP REGARDING DISPOSAL OF ANTIFREEZE TO THE STREET, HE DENIED IT AND SHOWED ME THAT THEY HAVE TANKS FOR STORAGE AND DISPOSAL OF HAZARDS MATERIAL.			
INITIAL ACTION	I DISTRIBUTED POLLUTION PREVENTION BROCHURES AT THIS PLAZA			



Address

4427 AVENIDA MANANA NE

Event ID

446

REPORTING SOURCE

Complaint Date

8/27/2014

CUSTOMER

JAME EISENBERG

311CASE ID

E-MAIL

e-mail

jeisenberg@cabq.gov

CUSTOMER Ph#

768-2654

SharePointLink:

<http://sharepoint.cabq.gov/dmd/storm/STORMWATER%20POLLUTION>

Description:

AFTER THE WALKTHROUGH FOR NEAR HEIGHT FLOOD CONTROL, CPN 549891, RAY SMITH (SOUDER, MILLER & ASSO.) MENTIONED THAT THEY HAD TELEVISED THE STORM DRAIN ALONG AVENIDA MANANA AND FOUND SIGNS OF RAW SEWAGE BETWEEN WASHINGTON AND AVENIDA LA RESOLANA.

Suspected Facility

HOME

Type of Complaint

SEWAGE

Inspection Date

12/1/2014

Number of Field Visits

1

Inspector

Facility Contact

RESIDENT ERICK

Facility Ph. #

c-977-4743 ph-292-4362

FIELD
OBSERVATION

THE RESIDENT TOLD ME THAT HE FIXED HIS COLLAPSED SANITARY LINE AROUND 4/19/2013.

INITIAL
ACTION

TV-INSPECTION OF THIS LINE IS PENDING.



Address

1417 OLD COORS SW

Event ID

430

REPORTING SOURCE

Complaint Date

9/12/2014

CUSTOMER

RAYMOND MONTOYA

311CASE ID

12950936

e-mail

CUSTOMER Ph#

877-6001

SharePointLink:

<http://sharepoint.cabq.gov/dmd/storm/STORMWATER%20POLLUTION>

Description:

CONCERNED CITIZEN WOULD LIKE THIS BUILDING REMOVED, ALSO THERE IS OVERGROWN VEGETATION (WEEDS/TREES) UP TO STREET BLOCKING CITIZENS BUSINESS SIGNS. FINALLY, THERE IS A LARGE OIL BARREL LEAKING ONTO PROPERTY.

Suspected Facility

BUILDING

Type of Complaint

TRASH

Inspection Date

9/15/2014

Number of Field Visits

1

Inspector

SK

Facility Contact

NA

Facility Ph. #

FIELD
OBSERVATION

NO VISIT, OUT OF CITY LIMIT

INITIAL
ACTION

THE CALLER OWNS THE HOME AT THIS OUTSIDE CITY LIMIT ADDRESS.HE NEEDS TO CALL THE COUNTY.



Address

BRIDGE AND 4TH ST SW

Event ID

429

REPORTING SOURCE

Complaint Date

9/16/2014

CUSTOMER

TONY ADAME

311CASE ID

12926314

e-mail

CUSTOMER Ph#

717-9873

SharePointLink:

<http://sharepoint.cabq.gov/dmd/storm/STORMWATER%20POLLUTION>

Description:

MOTOR OIL HAS BEEN SPILLED IN MCDONALDS PARKING LOT GOING INTO STORM DRAIN

Suspected Facility

AUTO ZONE BUSINESS

Type of Complaint

OIL

Inspection Date

9/17/2014

Number of Field Visits

1

Inspector

SK

Facility Contact

MANAGER

Facility Ph. #

FIELD
OBSERVATION

AUTOZONE MANAGER TOLD ME THAT SOMEONE LEFT USED MOTOR OIL NEAR THE DUMPSTER AND SHE DID TAKE CARE OF THE SPILLED OIL.THE OIL SPOTS WERE COVERED WITH ABSORBENT.

INITIAL
ACTION

I LEFT POLLUTION PREVENTION BROCHURES WITH THE AUTOZONE AND MCDONNELL'S MANAGERS.



Address	528 JUAN TABO NE		
Event ID	431	REPORTING SOURCE	Complaint Date 9/17/2014
CUSTOMER	ERIC MUNN	311CASE ID	E-MAIL e-mail holybarbarian@yahoo.com
CUSTOMER Ph#	688-2914	SharePointLink: http://sharepoint.cabq.gov/dmd/storm/STORMWATER%20POLLUTION	
Description:	CONSIDERING THE NATURE OF THIS BUSINESS, I WOULD LIKE YOU TO PROPOSE A BMP SUITED FOR THIS SITE.		
Suspected Facility	BUSINESS	Type of Complaint	OIL
Inspection Date	9/25/2014	Number of Field Visits	1 Inspector SK
Facility Contact	MANAGER	Facility Ph. #	
FIELD OBSERVATION	I SAW A FEW SMALL OIL SPOTS AT THE BACK OF THE BUILDING. THE OWNER CLAIMS THAT HE IS USING THIS PLACE TO STORE ANTIQYE CARS AND HE HAS NO OIL PROBLEMS.		
INITIAL ACTION	I LEFT P2 BROCHOURS AT THIS BUSINESSAND ASKED THEM TO KEEP THE PLACE CLEAN.		



Address	MIDAS AT 1129 JUAN TABO NE		
Event ID	432	REPORTING SOURCE	Complaint Date 9/29/2014
CUSTOMER	DANIEL GONZALES	311CASE ID	13012578, 13012947 e-mail
CUSTOMER Ph#	917-650-0135	SharePointLink: http://sharepoint.cabq.gov/dmd/storm/STORMWATER%20POLLUTION	
Description:	MIDAS IS POURING USED OIL NITO STORM DRAIN		
Suspected Facility	MIDAS AUTO	Type of Complaint	OIL
Inspection Date	9/30/2014	Number of Field Visits	1 Inspector SK
Facility Contact	MANAGER	Facility Ph. #	
FIELD OBSERVATION	THE MANAGER EXPLAINED TO ME THAT THERE WAS SOMEONE DRILLING NEAR THE INLET YESTERDAY TO INSTALL A SIGN NEXT TO HIS BUSINESS AND NONE OF HIS EMPLOYEE EVER DUMPED ANY OIL TO THE INLET.I DID NOT SEE ANY OIL AT THE INLET.		
INITIAL ACTION	I LEFT SOME P2 BROCHURES WITH THE MANAGER FOR HIS EMPLOYEES TO READ.		



Address	5809 JEFFERSON ST NE		
Event ID	433	REPORTING SOURCE	Complaint Date 10/2/2014
CUSTOMER	LEROY CORDOVA	311CASE ID WEB	e-mail leeleeinabq@yahoo.com
CUSTOMER Ph#	873-1542	SharePointLink: http://sharepoint.cabq.gov/dmd/storm/STORMWATER%20POLLUTION	
Description:	COOLENT AND SOLVENT LIQUIDS. ONGOING DUMPING MONTHLY FOR YEARS IN BACK DRAIN OF ENCLOSED YARD (NORTH SIDE).		
Suspected Facility	BACKERWORKS MANUFACTURING	Type of Complaint	HAZARDOUS MATERIAL
Inspection Date	10/6/2014	Number of Field Visits	1 Inspector SK
Facility Contact	MANAGER	Facility Ph. #	342-2943
FIELD OBSERVATION	I DID NOT SEE ANY EVIDENCE OF DUMPING TO THE STORM INLET		
INITIAL ACTION	THIS COMPANY HAS MSGP, I GAVE THE MANAGER POLLUTION PREVENTION BROCHURES.		



Address	4323 MESA GRANDE PL SE		
Event ID	443	REPORTING SOURCE	Complaint Date 10/10/2014
CUSTOMER	ABQ NEIGHBOR	311CASE ID 13055312	e-mail
CUSTOMER Ph#		SharePointLink: http://sharepoint.cabq.gov/dmd/storm/STORMWATER%20POLLUTION	
Description:	USED VEHICLE REPAIR BUSINESS ON STREET IN FRONT OF HOUSE. OIL, ANTIFREEZE ON STREET HTTP://SEECLICKFIX.COM/ISSUES/1316235		
Suspected Facility	HOME	Type of Complaint	OIL & ANTIFREEZE
Inspection Date	10/14/2014	Number of Field Visits	1 Inspector SK
Facility Contact	RESIDENT	Facility Ph. #	
FIELD OBSERVATION	THE RESIDENT TOLD ME THAT SHE HAD TRANSMISSION PROBLEM WITH HER CAR AND SOMEONE FROM THE CITY CAME BY AND CLEANED UP THE SPILLED OILS.I NOTICED THAT THE AREA HAS BEEN CLEANED UP.		
INITIAL ACTION	NO ACTION WAS NECESSARY. I LEFT POLLUTION PREVENTION BROCHURES AT THIS NEIGHBORHOOD.		



Address	9521 AVENIDA DEL OSO NE		
Event ID	434	REPORTING SOURCE	Complaint Date 10/15/2014
CUSTOMER	ALAN HILL	311CASE ID 13070365	e-mail
CUSTOMER Ph#	962-2385	SharePointLink: http://sharepoint.cabq.gov/dmd/storm/STORMWATER%20POLLUTION	
Description:	OWNERS OF PROPERTY DUMPING PAINT IN GUTTER AND ENDS UP IN SEWER		
Suspected Facility	HOME	Type of Complaint	SEDIMENT
Inspection Date	10/20/2014	Number of Field Visits 1	Inspector SK
Facility Contact	RESIDENT	Facility Ph. #	
FIELD OBSERVATION	THE SOURCE WAS FROM 9521 AVENIDA DEL OSO NE, THE WHITE RESIDUE ALONG THE GUTTER WAS THE WASHED LIME RESIDUE ON THE SWIMMING POOL FILTER, THE RESIDENT THOUGHT IT WAS OKAY TO WASH THE FILTER ON THE STREET.		
INITIAL ACTION	I ASKED HIM TO STOP DOING THIS IN THE FUTURE AND I DISTRIBUTED POLLUTION PREVENTION BROCHURES AT THIS NEIGHBORHOOD.		



Address

REDBURN TIRE CO. AT 2645 BAYLOR SE

Event ID

437

REPORTING SOURCE

Complaint Date

10/23/2014

CUSTOMER

MARK KELLY

311CASE ID

E-MAIL

e-mail

mkelly@abcwua.org

CUSTOMER Ph#

382-2914

SharePointLink:

<http://sharepoint.cabq.gov/dmd/storm/STORMWATER%20POLLUTION>

Description:

ONE OF OUR CREWS NOTICED THIS STORMWATER DISCHARGE. THE ADDRESS IS 2645 BAYLOR DR SE. THOUGHT YOU WOULD WANT TO KNOW.SEE THE ATTACHED PICTURES.

Suspected Facility

REDBURN TIRE CO.

Type of Complaint

HAZARDOUS MATERIAL

Inspection Date

10/24/2014

Number of Field Visits

1

Inspector

SK

Facility Contact

MANAGER

Facility Ph. #

344-2300

FIELD
OBSERVATION

THE MANAGER TOLD ME THAT ONE OF HIS EMPLOYEES WASHED AN EMPTY 55 GALLON CONTAINER (OF WATER BASED TIRE PAINT) AND IT DRAINED TO THE STREET.

INITIAL
ACTION

THEY DID CLEANED UP THE AREA AND DISCIPLINED THE EMPLOYEE WHO DID THAT. THE MANAGER GAVE ME A COPY OF MSDS FOR THIS PRODUCT WHICH INDICATES IT IS SAFE.



Address	224 SAN PASQUAL SW		
Event ID	436	REPORTING SOURCE	Complaint Date 10/24/2014
CUSTOMER	KEVIN DAGGETT	311CASE ID	E-MAIL kdaggett@cabq.gov
CUSTOMER Ph#	768-2778	SharePointLink: http://sharepoint.cabq.gov/dmd/storm/STORMWATER%20POLLUTION	
Description: DIRT IS BEING TRACKED AND A BICYCLIST ALMOST SLIPPED ON THE MUD.			
Suspected Facility	GARCIA'S KITCHEN CONSTRUCTION	Type of Complaint	CONSTRUCTION
Inspection Date	10/27/2014	Number of Field Visits	1 Inspector SK
Facility Contact	SUPERINTENDENT	Facility Ph. #	
FIELD OBSERVATION	THE TRACKED MUD WAS VISIBLE COMING FROM THIS SITE.		
INITIAL ACTION	THE SUPERINTENDENT ASKED THE WORKER TO SWEEP THE AREA AND IMPROVE THE BMP OF THE SITE ENTRANCE.		



Address	101 ANDERSON SE		
Event ID	439	REPORTING SOURCE	Complaint Date 10/25/2014
CUSTOMER	STEVEN ABEYTA	311CASE ID 13110481	e-mail
CUSTOMER Ph#	244-9395	SharePointLink: http://sharepoint.cabq.gov/dmd/storm/STORMWATER%20POLLUTION	
Description:	CITIZEN REPORTING OIL OR FUEL SPILL AT ADDRESS ADVISED AIR QUALITY WILL NOT GO OUT TO CLEAN. CITIZEN INSISTED IT BE REPORTED SINCE HE CAN SMELL IT.		
Suspected Facility	BIG BEAR PETROLEUM	Type of Complaint	OIL
Inspection Date	10/29/2014	Number of Field Visits	1 Inspector SK
Facility Contact	MANAGER	Facility Ph. #	250-3816
FIELD OBSERVATION	I SAW SEVERAL OIL SPOTS COVERED WITH ABSORBENT. THE MANAGER TOLD ME THAT A CUSTOMER SPILLED SOME USED OIL BY ACCIDENT AND THEY COVERED IT WITH ABSORBENT. ALSO HE SHOWED ME THEIR OPERATIONS & MAINTENANCE PLAN MANUAL.		
INITIAL ACTION	I GAVE THE MANAGER SEVERAL COPIES OF POLLUTION PREVENTION BROCHURES FOR HIS EMPLOYEES.		



Address

7400 BEVERLY HILLS NE

Event ID

435

REPORTING SOURCE

Complaint Date

10/26/2014

CUSTOMER

LORENZO PEREZ

311CASE ID

WEB

e-mail

tlcperez1@yahoo.com

CUSTOMER Ph#

857-9677

SharePointLink:

<http://sharepoint.cabq.gov/dmd/storm/STORMWATER%20POLLUTION>

Description:

CALLED SOLID WASTE

Suspected Facility

SIDEWALK-STREET

Type of Complaint

TRASH

Inspection Date

10/27/2014

Number of Field Visits

1

Inspector

Facility Contact

NA

Facility Ph. #

na

FIELD
OBSERVATION

THERE WERE A LOT OF CARDBOARDS AND TRASH ON THE CURB AND STREET AT THIS LOCATION

INITIAL
ACTION

I ASKED THE SOLID WASTE DIVISION TO PICK UP THOSE ITEMS AND THEY DID.



Address	7321 VIVIAN NE		
Event ID	438	REPORTING SOURCE	Complaint Date 10/27/2014
CUSTOMER	ROBERT KNOLLS	311CASE ID 13110168	e-mail
CUSTOMER Ph#	797-0422	SharePointLink: http://sharepoint.cabq.gov/dmd/storm/STORMWATER%20POLLUTION	
Description:	A1 CARPET CLEANING IS EMPTING THE WATER CONTAINING CHEMICALS FROM THEIR CARPET CLEANING BOX COMMERCIAL TRUCK ALONG THE CURB AREA. HE IS CONCERNED BECAUSE OF THE CHEMICALS.		
Suspected Facility	STREET	Type of Complaint	CARPET CLEANING
Inspection Date	10/27/2014	Number of Field Visits 1	Inspector SK
Facility Contact	RESIDENT	Facility Ph. #	
FIELD OBSERVATION	I SPOKE TO THE RESIDENT REGARDING THE INCIDENT AND SHE TOLD ME THAT THEY DUMPED CLEAN WATER TANK ONLY. THERE WERE NO STORM INLETS AT THIS AREA AND THE STREET (AND THE GUTTER) WAS CLEAN.		
INITIAL ACTION	I GIVE HER AND OTHER NEIGHBOR SOME POLLUTION PREVENTION BROCHURES.		



Address	6313 BELCHER NE		
Event ID	440	REPORTING SOURCE	Complaint Date 11/4/2014
CUSTOMER	MARY VILLANUEVA	311CASE ID 13146049	e-mail
CUSTOMER Ph#	507-5263	SharePointLink: http://sharepoint.cabq.gov/dmd/storm/STORMWATER%20POLLUTION	
Description:	CITIZEN SAID HER NEIGHBOR HAS A CARPET CLEANING BUSINESS AND AT NIGHT THEY DUMP ALL OF THE DIRTY WATER ON THE STREET AND IT RUNS DOWN AND INTO THE INLET GRATES CITIZEN WOULD LIKE TO KNOW IF THIS IS ILLEGAL.		
Suspected Facility		Type of Complaint	CARPET CLEANING
Inspection Date	11/5/2014	Number of Field Visits	1
Facility Contact		Inspector	SK
Facility Ph. #			
FIELD OBSERVATION	THERE WERE SOME INDICATIONS OF DUMPING CARPET CLEANING WASTE WATER IN FRONT OF THIS ADDRESS.		
INITIAL ACTION	I WENT TO THIS ADDRESS BUT NOBODY WAS HOME. I DISTRIBUTED POLLUTION PREVENTION BROCHURES AT THIS NEIGHBORHOOD		



Address

6023 LEGENDS NW

Event ID

441

REPORTING SOURCE

Complaint Date

11/4/2014

CUSTOMER

ANONYMOUS

311CASE ID

13146760

e-mail

CUSTOMER Ph#

na

SharePointLink:

<http://sharepoint.cabq.gov/dmd/storm/STORMWATER%20POLLUTION>

Description: OIL IN DRIVEWAY AND IN STREET, CONSTANT ISSUE

Suspected Facility

STREET

Type of Complaint

OIL

Inspection Date

11/6/2014

Number of Field Visits

1

Inspector

SK

Facility Contact

RESIDENT

Facility Ph. #

FIELD
OBSERVATION

THERE WERE MINOR OIL SPOTS ON THE DRIVEWAY AND THE STREET.

INITIAL
ACTION

I COVERED THE OIL SPOTS IN THE STREET WITH ABSORBENT AND AS ASKED THE RESIDENT TO SWEEP IT NEXT DAY. ALSO, I DISTRIBUTED POLLUTION PREVENTION BROCHURES AT THIS NEIGHBORHOOD



Address

6704 GLENRIO NW

Event ID

442

REPORTING SOURCE

Complaint Date

11/5/2014

CUSTOMER

ANDREW SANCHEZ

311CASE ID

E-MAIL

e-mail

asanchez@cabq.gov

CUSTOMER Ph#

304-1309

SharePointLink:

<http://sharepoint.cabq.gov/dmd/storm/STORMWATER%20POLLUTION>

Description: MUD IN THE STREET AT THIS CONSTRUCTION SITE

Suspected Facility

GLENRIO APARTMENTS CONST

Type of Complaint

CONSTRUCTION

Inspection Date

11/6/2014

Number of Field Visits

1

Inspector

SK

Facility Contact

SUPERINTENDENT

Facility Ph. #

FIELD
OBSERVATION

THERE WAS SOME DIRT AND MUD COMING OUT FROM SITE TO THE STREET.

INITIAL
ACTION

THIS CONSTRUCTION SITE HAS NOI AND THEIR SWPPP WAS POSTED ON THE BOARD. I ASKED THE SUPERINTENDENT TO IMPROVE THE MUD TRACKING BMP AT THE ENTRANCE AND SWEEP THE STREET. HE ASKED HIS EMPLOYEES TO FIX THE ENTRANCE AND SWEEP THE AREA.



Address

8212 CALLE AVION NE

Event ID

444

REPORTING SOURCE

Complaint Date

12/2/2014

CUSTOMER

HERMAN GALLEGOS

311CASE ID

13219146

e-mail

CUSTOMER Ph#

797-5441

SharePointLink:

Description: VEHICL LEAKING OIL

Suspected Facility

STREET

Type of Complaint

OIL

Inspection Date

12/1/2014

Number of Field Visits

1

Inspector

SK

Facility Contact

RESIDENT

Facility Ph. #

na

FIELD
OBSERVATION

THE OIL SPOTS WERE MINOR, TYPICAL OF MOST PARKING AREAS.

INITIAL
ACTION

THERE WAS NO NEED THE DRIED OIL TO BE COVERED WITH ABSORBENT. I DISTRIBUTED POLLUTION PREVENTION BROCHURES AT THIS NEIGHBORHOOD.



Address	5310 SAN MATEO NE-FRANK'S POWER EQ				
Event ID	445	REPORTING SOURCE	Complaint Date		12/8/2014
CUSTOMER	ANONYMOUS	311CASE ID	PH-CALL TO KF	e-mail	
CUSTOMER Ph#		SharePointLink: http://sharepoint.cabq.gov/dmd/storm/STORMWATER%20POLLUTION			
Description:	ENGINE WASH				
Suspected Facility	FRANK'S POWER EQUIPMENTS	Type of Complaint		OIL	
Inspection Date	12/9/2014	Number of Field Visits	1	Inspector	SK
Facility Contact	OWNER-MANAGER	Facility Ph. #	872-2535		
FIELD OBSERVATION	THEY HAVE AN AREA THAT THEY POWERWASH EQUIPMENT THAT DRAINS TO STORM DRAIN.THIS BUSINESS HAS A SHOP FOR SMALL ENGINE REPAIR.THEY ARE CALSSIFIED AS SIC CODE 526109 LAWN MOWERS, NOT REQUIRED TO HAVE INDUSTRIAL PERMIT.				
INITIAL ACTION	LEFT POLLUTION PREVENTION BROCHURES WITH THE MANAGER AND TOLD HIM THAT POWERWASHING ENIGNS AT THE STORM INLET IS NOT ACCEOTABLE.				

